

K&M Home Inspection

2617 E Paladin Ave Anaheim CA 92806
Tel: 714-323-3414
gdmusc@yahoo.com

CONFIDENTIAL INSPECTION REPORT

PREPARED FOR:

[REDACTED]

INSPECTION ADDRESS

[REDACTED]

INSPECTION DATE

8/15/2016 10:00 am to 12:30 pm



This report is the exclusive property of the Inspection Company and the client whose name appears herewith, and its use by any unauthorized persons is prohibited.

GENERAL INFORMATION

Inspection Address: 3488Grand Teton Dr, Corona, CA 92881
Inspection Date: 8/15/2016 Time: 10:00 am to 12:30 pm
Weather: Clear and Dry - Temperature at time of inspection: 80-90 Degrees
Humidity at time of inspection: 25%

Inspected by: Gerardo "Jerry" Duarte

Client Information: Realtor - Yolanda Soloria
12651Newport Ave, Tustin, CA 92780
Phone: 714-731-3777
Mobile: 714-2709274
EMail: Yolanda @sevengables.com

Structure Type: Wood Frame
Foundation Type: Slab
Furnished: Yes
Number of Stories: two

Structure Style: California Ranch

Structure Orientation: North East

Estimated Year Built: 1998
Unofficial Sq.Ft.: 3000

People on Site At Time of Inspection: Buyer(s)
Seller(s)
Buyer's Agent
Owners

PLEASE NOTE:

This report is the exclusive property of [insert your company name] and the client whose name appears herewith, and its use by any unauthorized persons is strictly prohibited.

The observations and opinions expressed within this report are those of [insert your company name] and supercede any alleged verbal comments. We inspect all of the systems, components, and conditions described in accordance with the standards of [insert the name of the organization to which you belong], and those that we do not inspect are clearly disclaimed in the contract and/or in the aforementioned standards. However, some components that are inspected and found to be functional may not necessarily appear in the report, simply because we do not wish to waste our client's time by having them read an unnecessarily lengthy report about components that do not need to be serviced.

In accordance with the terms of the contract, the service recommendations that we make in this report should be completed well before the close of escrow by licensed specialists, who may well identify additional defects or recommend some upgrades that could affect your evaluation of the property.

Report File: 3488 Grand Teton Dr

SCOPE OF WORK

You have contracted with K&M Home Inspection to perform a generalist inspection in accordance with the standards of practice established by NAHI (National Association of Home Inspectors), a copy of which is available upon request. Generalist inspections are essentially visual, and distinct from those of specialists, inasmuch as they do not include the use of specialized instruments, the dismantling of equipment, or the sampling of air and inert materials. Consequently, a generalist inspection and the subsequent report will not be as comprehensive, nor as technically exhaustive, as that generated by specialists, and it is not intended to be. The purpose of a generalist inspection is to identify significant defects or adverse conditions that would warrant a specialist evaluation. Therefore, you should be aware of the limitations of this type of inspection, which are clearly indicated in the standards. However, the inspection is not intended to document the type of cosmetic deficiencies that would be apparent to the average person, and certainly not intended to identify insignificant deficiencies. Similarly, we do not inspect for vermin infestation, which is the responsibility of a licensed exterminator.

Most homes built after 1978, are generally assumed to be free of asbestos and many other common environmental contaminants. However, as a courtesy to our clients, we are including some well documented, and therefore public, information about several environmental contaminants that could be of concern to you and your family, all of which we do not have the expertise or the authority to evaluate, such as asbestos, radon, methane, formaldehyde, termites and other wood-destroying organisms, pests and rodents, molds, microbes, bacterial organisms, and electromagnetic radiation, to name some of the more commonplace ones. Nevertheless, we will attempt to alert you to any suspicious substances that would warrant evaluation by a specialist. However, health and safety, and environmental hygiene are deeply personal responsibilities, and you should make sure that you are familiar with any contaminant that could affect your home environment. You can learn more about contaminants that can affect your home from a booklet published by The Environmental Protection Agency, which you can read online at www.epa.gov/iaq/pubs/insidest.htm.

Mold is one such contaminant. It is a microorganism that has tiny seeds, or spores, that are spread on the air then land and feed on organic matter. It has been in existence throughout human history, and actually contributes to the life process. It takes many different forms, many of them benign, like mildew. Some characterized as allergens are relatively benign but can provoke allergic reactions among sensitive people, and others characterized as pathogens can have adverse health effects on large segments of the population, such as the very young, the elderly, and people with suppressed immune systems. However, there are less common molds that are called toxigens that represent a serious health threat. All molds flourish in the presence of moisture, and we make a concerted effort to look for any evidence of it wherever there could be a water source, including that from condensation. Interestingly, the molds that commonly appear on ceramic tiles in bathrooms do not usually constitute a health threat, but they should be removed. However, some visibly similar molds that form on cellulose materials, such as on drywall, plaster, and wood, are potentially toxigenic. If mold is to be found anywhere within a home, it will likely be in the area of tubs, showers, toilets, sinks, water heaters, evaporator coils, inside attics with unvented bathroom exhaust fans, and return-air compartments that draw outside air, all of which are areas that we inspect very conscientiously. Nevertheless, mold can appear as though spontaneously at any time, so you should be prepared to monitor your home, and particularly those areas that we identified. Naturally, it is equally important to maintain clean air-supply ducts and to change filters as soon as they become soiled, because contaminated ducts are a common breeding ground for dust mites, rust, and other contaminants. Regardless, although some mold-like substances may be visually identified, the specific identification of molds can only be determined by specialists and laboratory analysis, and is absolutely beyond the scope of our inspection. Nonetheless, as a prudent investment in environmental hygiene, we categorically recommend that you have your home tested for the presence of any such contaminants, and particularly if you or any member of your family suffers from allergies or asthma. Also, you can learn more about mold from an Environmental Protection Agency document entitled "A Brief Guide to Mold, Moisture and Your Home," by visiting their web site at: <http://www.epa.gov/iaq/molds/moldguide.html>, from which it can be downloaded.

Asbestos is a notorious contaminant that could be present in any home built before 1978. It is a naturally occurring mineral fiber that was first used by the Greek and Romans in the first century, and it has been widely used throughout the modern world in a variety of thermal insulators, including those in the form of paper wraps, bats, blocks, and blankets. However, it can also be found in a wide variety of other products too numerous to

mention, including duct insulation and acoustical materials, plasters, siding, floor tiles, heat vents, and roofing products. Although perhaps recognized as being present in some documented forms, asbestos can only be specifically identified by laboratory analysis. The most common asbestos fiber that exists in residential products is chrysotile, which belongs to the serpentine or white-asbestos group, and was used in the clutches and brake shoes of automobiles for many years. However, a single asbestos fiber is said to be able to cause cancer, and is therefore a potential health threat and a litigious issue. Significantly, asbestos fibers are only dangerous when they are released into the air and inhaled, and for this reason authorities such as the Environmental Protection Agency [EPA] and the Consumer Product Safety Commission [CPSC] distinguish between asbestos that is in good condition, or non-friable, and that which is in poor condition, or friable, which means that its fibers could be easily crumbled and become airborne. However, we are not specialists and, regardless of the condition of any real or suspected asbestos-containing material [ACM], we would not endorse it and recommend having it evaluated by a specialist.

Radon is a gas that results from the natural decay of radioactive materials within the soil, and is purported to be the second leading cause of lung cancer in the United States. The gas is able to enter homes through the voids around pipes in concrete floors or through the floorboards of poorly ventilated crawlspaces, and particularly when the ground is wet and the gas cannot easily escape through the soil and be dispersed into the atmosphere. However, it cannot be detected by the senses, and its existence can only be determined by sophisticated instruments and laboratory analysis, which is completely beyond the scope of our service. However, you can learn more about radon and other environmental contaminants and their affects on health, by contacting the Environmental Protection Agency (EPA), at www.epa.gov/radon/images/hmbuygud.pdf, and it would be prudent for you to enquire about any high radon readings that might be prevalent in the general area surrounding your home.

Lead poses an equally serious health threat. In the 1920's, it was commonly found in many plumbing systems. In fact, the word "plumbing" is derived from the Latin word "plumbum," which means lead. When in use as a component of a waste system, it is not an immediate health threat, but as a component of potable water pipes it is a definite health-hazard. Although rarely found in modern use, lead could be present in any home build as recently as the nineteen forties. For instance, lead was an active ingredient in many household paints, which can be released in the process of sanding, and even be ingested by small children and animals chewing on painted surfaces. Fortunately, the lead in painted surfaces can be detected by industrial hygienists using sophisticated instruments, but testing for it is not cheap. There are other environmental contaminants, some of which we have already mentioned, and others that may be relatively benign. However, we are not environmental hygienists, and as we stated earlier we disclaim any responsibility for testing or establishing the presence of any environmental contaminant, and recommend that you schedule whatever specialist inspections that may deem prudent within the contingency period.

Exterior

With the exception of townhomes, condominiums, and residences that are part of a planned urban development, or PUD, we evaluate the following exterior features: driveways, walkways, fences, gates, handrails, guardrails, yard walls, carports, patio covers, decks, building walls, fascia and trim, balconies, doors, windows, lights, and outlets. However, we do not evaluate any detached structures, such as storage sheds and stables, and we do not water test or evaluate subterranean drainage systems or any mechanical or remotely controlled components, such as driveway gates. Also, we do not evaluate landscape components, such as trees, shrubs, fountains, ponds, statuary, pottery, fire pits, patio fans, heat lamps, and decorative or low-voltage lighting. In addition, we do not comment on coatings or cosmetic deficiencies and the wear and tear associated with the passage of time, which would be apparent to the average person. However, cracks in hard surfaces can imply the presence of expansive soils that can result in continuous movement, but this could only be confirmed by a geological evaluation of the soil.

Site & Other Observations

Renovations & Additions

Informational Conditions

The property has been renovated or remodeled. Therefore, you should request documentation that should include permits and any warranties or guarantees that might be applicable, because we do not approve or tacitly endorse any work done without permits, and latent defects could exist.

Landscaping Observations

Informational Conditions

There are trees on this property that we do not have the expertise to evaluate, but which you may wish to have evaluated by an arborist.



There are trees on this property that we do not have the expertise to evaluate - *Continued*



We do not evaluate landscaping, but some of the trees need to be trimmed or pruned.

Grading & Drainage

General Comments

Functional Components and Conditions

Drainage needs to be added to the back yard of property for proper water drainage and flooding

Informational Conditions

Water can be destructive and foster conditions that are deleterious to health. For this reason, the ideal property will have soils that slope away from the residence and the interior floors will be several inches higher than the exterior grade. Also, the residence will have roof gutters and downspouts that discharge into area drains with catch basins that carry water away to hard surfaces. However, we cannot guarantee the condition of any subterranean drainage system, but if a property does not meet this ideal, or if any portion of the interior floor is below the exterior grade, we cannot endorse it and recommend that you consult with a grading and drainage contractor, even though there may not be any evidence of moisture intrusion. The sellers or occupants will obviously have a more intimate knowledge of the site than we could possibly hope to have during our limited visit, however we have confirmed moisture intrusion in residences when it was raining that would not have been apparent otherwise. Also, in conjunction with the cellulose material found in most modern homes, moisture can facilitate the growth of biological organisms that can compromise building materials and produce mold-like substances that can have an adverse affect on health.

Moisture & Related Issues

Informational Conditions

Moisture intrusion is a perennial problem, with which you should be aware. It involves a host of interrelated factors, and can be unpredictable, intermittent, or constant. When moisture intrusion is not self evident, it can be inferred by musty odors, peeling paint or plaster, efflorescence, or salt crystal formations, rust on metal components, and wood rot. However, condensation and humidity can produce similar conditions if the temperature in an area is not maintained above the dew point. Regardless, if the interior floors of a residence are at the same elevation or lower than the exterior grade we could not rule out the potential for moisture intrusion and would not endorse any such areas. Nevertheless, if such conditions do exist, or if you or any member of your family suffers from allergies or asthma, you should schedule a specialist inspection.

Area Drains

Informational Conditions

The property is served by area drains that appear to be in acceptable condition. However, because it is impossible to see inside them, the seller should guarantee that the drains are functional, or they should be flushed through to the street before the close of escrow. Surface water carries minerals and silt that is

deposited inside the pipes and hardens in the summer months to the consistency of wet concrete, which can impede drainage and require the pipes to be cleared by a roter service.

House Wall Finish

House Wall Finish Type

Informational Conditions

The house walls are finished with stucco.

House Wall Finish Observations

Functional Components and Conditions

Evidence of moisture in the stucco and should be fixed by a licensed contractor.



Informational Conditions

The house wall finish is in acceptable condition.

Exterior Components

General Comments

Informational Conditions

It is important to maintain a property, including painting or sealing walkways, decks, and other hard surfaces, and it is particularly important to keep the house walls sealed, which provide the only barrier against deterioration. Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principle cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not have been apparent otherwise. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior, because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Unfortunately, this is not always apparent, which is why we disclaim an evaluation of hermetic seals. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows, and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

General Exterior Comments - *Continued*



Driveways

Informational Conditions

The driveway is in acceptable condition.

Walkways

Informational Conditions

The walkways are in acceptable condition.

Yard Walls

Informational Conditions

The yard walls may have some cosmetic damage but are functional.

Fences & Gates

Functional Components and Conditions

The gates are rubbing on the concrete floor and recommend service



Informational Conditions

Sections of the wrought iron fence have typical rust damage and should be serviced or monitored.

Components and Conditions Needing Service

The gates needs typical maintenance-type service, to open and close or latch easily.



Sections of the fence are leaning or damaged and should be repaired or replaced.

Fascia & Trim

Informational Conditions

The fascia board and trim are in acceptable condition.

Exterior Wooden Doors

Informational Conditions

The exterior doors are in acceptable condition.

The exterior doors are in acceptable condition - *Continued*



Windows

Informational Conditions

The windows are in acceptable condition. However, in accordance with industry standards, we do not test every window in the house, and particularly if the house is furnished. We do test every unobstructed window in every bedroom to ensure that at least one facilitates an emergency exit.

Screens

Informational Conditions

The window screens are functional.

Outlets

Informational Conditions

The outlets that were tested are functional and include ground-fault protection.

Lights

Informational Conditions

The lights outside the doors of the residence are functional. However, we do not inspect or evaluate decorative lights.

Structural

All structures are dependent on the soil beneath them for support, but soils are not uniform. Some that might appear to be firm and solid can liquefy and become unstable during seismic activity. Also, there are soils that can expand to twice their volume with the influx of water and move structures with relative ease, raising and lowering them and fracturing slabs and other hard surfaces. In fact, expansive soils have accounted for more structural damage than most natural disasters. Regardless, foundations are not uniform, and conform to the structural standard of the year in which they were built. In accordance with our standards of practice, we identify foundation types and look for any evidence of structural deficiencies. However, cracks or deteriorated surfaces in foundations are quite common. In fact, it would be rare to find a raised foundation wall that was not cracked or deteriorated in some way, or a slab foundation that did not include some cracks concealed beneath the carpeting and padding. Fortunately, most of these cracks are related to the curing process or to common settling, including some wide ones called cold-joint separations that typically contour the footings, but others can be more structurally significant and reveal the presence of expansive soils that can predicate more or less continual movement. We will certainly alert you to any suspicious cracks if they are clearly visible. However, we are not specialists, and in the absence of any major defects we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert.

Various Hard Surfaces

Common Observations

Informational Conditions

There are common settling, or curing, cracks in the hard surfaces. This is somewhat predictable, and is typically not regarded as being structurally significant, but we are not specialists and you may wish to have this confirmed by one.

Structural Elements

Identification of Wall Structure

Informational Conditions

The walls are conventionally framed with wooden studs.

Identification of Floor Structure

Informational Conditions

The floor structure consists of a poured slab that could include reinforcing steel.

Identification of Ceiling Structure

Informational Conditions

The ceiling structure consists of standard joists.

Identification of Roof Structure

Informational Conditions

The roof structure is conventionally framed with rafters, purlins, collar-ties, et cetera.

Slab Foundation

General Comments

Informational Conditions

This residence has a slab foundation. Such foundations vary considerably from older ones that have no moisture barrier under them and no reinforcing steel within them to newer ones that have both. Our inspection of slab foundations conforms to industry standards, which is that of a generalist and not a specialist. We check the visible portion of the stem walls on the outside for any evidence of significant cracks or structural deformation, but we do not move furniture or lift carpeting and padding to look for cracks or moisture penetration, and we do not use any of the specialized devices that are used to establish relative elevations and confirm differential movement. Significantly, many slabs are built or move out of level, but the average person may not become aware of this until there is a difference of more than one inch in twenty feet, which most authorities regard as being tolerable.

Many slabs are found to contain cracks when the carpet and padding are removed, including some that contour the edge and can be quite wide. They typically result from shrinkage and usually have little structural significance. However, there is no absolute standard for evaluating cracks, and those that are less than 1/4" and which exhibit no significant vertical or horizontal displacement are generally not regarded as being significant. Although they typically do result from common shrinkage, they can also be caused by a deficient mixture of concrete, deterioration through time, seismic activity, adverse soil conditions, and poor drainage, and if they are not sealed they can allow moisture to enter a residence, and particularly if the residence is surcharged by a hill or even a slope, or if downspouts discharge adjacent to the slab. However, in the absence of any major defects, we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert, and we would be happy to refer one.

Method of Evaluation

Informational Conditions

We evaluated the slab foundation on the exterior, by examining the stem walls that project above the footing at the base of the house walls. The interior portions of the slab, which is also known as the slab floor, have little structural significance and, inasmuch as they are covered and not visually accessible, it is beyond the scope of

our inspection.

Common Observations

Informational Conditions

The residence has a bolted, slab foundation with no visible or significant abnormalities.

Roof/Attic

There are many different roof types, which we evaluate by walking on their surfaces. If we are unable or unwilling to do this for any reason, we will indicate the method that was used to evaluate them. Every roof will wear differently relative to its age, the number of its layers, the quality of its material, the method of its application, its exposure to direct sunlight or other prevalent weather conditions, and the regularity of its maintenance. Regardless of its design-life, every roof is only as good as the waterproof membrane beneath it, which is concealed and cannot be examined without removing the roof material, and this is equally true of almost all roofs. In fact, the material on the majority of pitched roofs is not designed to be waterproof only water-resistant. However, what remains true of all roofs is that, whereas their condition can be evaluated, it is virtually impossible for anyone to detect a leak except as it is occurring or by specific water tests, which are beyond the scope of our service. Even water stains on ceilings, or on the framing within attics, could be old and will not necessarily confirm an active leak without some corroborative evidence, and such evidence can be deliberately concealed. Consequently, only the installers can credibly guarantee that a roof will not leak, and they do. We evaluate every roof conscientiously, and even attempt to approximate its age, but we will not predict its remaining life expectancy, or guarantee that it will not leak. Naturally, the sellers or the occupants of a residence will generally have the most intimate knowledge of the roof and of its history. Therefore, we recommend that you ask the sellers about it, and that you either include comprehensive roof coverage in your home insurance policy, or that you obtain a roof certification from an established local roofing company.

Concrete Tile Roof

General Comments

Informational Conditions

Concrete tile roofs are among the most expensive and durable of all roofs, and are warranted by the manufacturer to last for forty years or more, but are usually only guaranteed against leaks by the installer from three to five years. Like other pitched roofs, they are not designed to be waterproof, only water resistant, and are dependant on the integrity of the waterproof membrane beneath them, which cannot be seen without removing the tiles, but which can be split by movement, deteriorated through time, or by ultra-violet contamination. Significantly, although there is some leeway in installation specifications, the type and quality of membranes that are installed can vary from one installer to another, and leaks do occur. The majority of leaks result when a roof has not been well maintained or kept clean, and we recommend servicing them annually. Most residences have termite inspections as a condition of escrow, and when termite infestation is confirmed most are commonly tented in preparation for fumigation. This requires personnel to walk on the roof, which can damage the roofing material. Therefore it is essential that you review the termite report, and if the residences is to be tented that you have a local roofing company inspect the roof after the tenting has been removed to confirm that the roofing material did not sustain damage.

Method of Evaluation

Functional Components and Conditions

A licensed roofer is recommended to evaluate the roof.

Informational Conditions

We were unable to access the second-story roof due to its height, and evaluated with the use of binoculars from various vantage points.

We were unable to access the second-story roof due to its height - *Continued*



We elected not to walk the roof because the roofing material is easily broken, and evaluated it from several other vantage points.

Estimated Age

Informational Conditions

The roof appears to be the same age as the residence, or 18 years old.

Roofing Material

Informational Conditions

The roof is in acceptable condition, but this is not a guarantee against leaks. For a guarantee, you would need to have a roofing company perform a water-test and issue a roof certification.

Gutters & Drainage

Functional Components and Conditions

The gutters appear to be in acceptable condition. However, without water in them it is difficult to judge whether they are correctly pitched to direct water into the downspouts, but they should function as they were intended.

Chimney

The Chimney Safety Institute of America has published industry standards for the inspection of chimneys, and on January 13, 2000, the National Fire Protection Association adopted these standards as code, known as NFPA 211. Our inspection of masonry and factory-built chimneys to what is known as a Level-One inspection, which is purely visual and not to be confused with Level-Two, and Level-Three inspections, which are performed by qualified specialists with a knowledge of codes and standards, and typically involves dismantling components and/or investigations with video-scan equipment and other means to evaluate chimneys.

Family Room Chimney

General Prefabricated

Informational Conditions

There are a wide variety of pre-fabricated chimneys, which are constructed on site with approved components. We perform a competent inspection of them, but we are not specialists, and our inspection of them is limited to those areas that can be viewed without dismantling any portion of them, and we cannot guarantee that any particular component is the one stipulated for use by the manufacturer. For instance, experience has taught us that many prefabricated chimneys have been fitted with architectural shrouds that are not approved by the manufacturer, and which can inhibit drafting and convectional cooling. However, we recommend a level-two inspection by a qualified specialist within the contingency period or before the close of escrow, as recommended by NAPA standards "upon the sale or transfer of a property."

Common Observations

Informational Conditions

The chimney walls appear to be in acceptable condition.



Weather Cap-Spark Arrestor

Informational Conditions

The chimney has a functional weather cap/spark arrestor.

Crown or Termination Cap

Informational Conditions

The crown, which is designed to seal the chimney wall and to shed rainwater and thereby prevent moisture from deteriorating the chimney, is in acceptable condition.

Chimney Flashings

Informational Conditions

The chimney flashings are in acceptable condition.

Chimney Flue

Informational Conditions

The portions of the flue that are visible appear to be in acceptable condition.

Flue Chase

Informational Conditions

There is a functional chase that surrounds the chimney flue as it passes through the attic.

Fireplace

Informational Conditions

The fireplace is in acceptable condition.

Damper

Informational Conditions

The damper is functional.

Ash Box

Informational Conditions

The ash box is functional, and should be kept clear and clean.

Glass Doors

Informational Conditions

The fireplace glass doors are functional.

Mantle

Informational Conditions

The fireplace mantle is in acceptable condition.

Plumbing

Plumbing systems have common components, but they are not uniform. In addition to fixtures, these components include gas pipes, water pipes, pressure regulators, pressure relief valves, shut-off valves, drain and vent pipes, and water-heating devices, some of which we do not test if they are not in daily use. The best and most dependable water pipes are copper, because they are not subject to the build-up of minerals that bond within galvanized pipes, and gradually restrict their inner diameter and reduce water volume. Water softeners can remove most of these minerals, but not once they are bonded within the pipes, for which there would be no remedy other than a re-pipe. The water pressure within pipes is commonly confused with water volume, but whereas high water volume is good high water pressure is not. In fact, whenever the street pressure exceeds eighty pounds per square inch a regulator is recommended, which typically comes factory preset between forty-five and sixty-five pounds per square inch. However, regardless of the pressure, leaks will occur in any system, and particularly in one with older galvanized pipes, or one in which the regulator fails and high pressure begins to stress the washers and diaphragms within the various components.

Waste and drainpipes pipes are equally varied, and range from modern ABS ones [acrylonitrile butadiene styrene] to older ones made of cast-iron, galvanized steel, clay, and even a cardboard-like material that is coated with tar. The condition of these pipes is usually directly related to their age. Older ones are subject to damage through decay and root movement, whereas the more modern ABS ones are virtually impervious to damage, although some rare batches have been alleged to be defective. However, inasmuch as significant portions of drainpipes are concealed, we can only infer their condition by observing the draw at drains. Nonetheless, blockages will occur in the life of any system, but blockages in drainpipes, and particularly in main drainpipes, can be expensive to repair, and for this reason we recommend having them video-scanned. This could also confirm that the house is connected to the public sewer system, which is important because all private systems must be evaluated by specialists.

Potable Water Supply Pipes

Water Main Shut-off Location

Informational Conditions

The main water shut-off valve is located at the front of the residence.

Pressure Regulators

Informational Conditions

A functional pressure regulator is in place on the plumbing system.

Pressure Relief Valves

Components and Conditions Needing Service

The pressure relief valve at the main is dripping. The regulator should be checked to see if it has failed, or the relief valve should be replaced.

The pressure relief valve at the main is dripping and may need to be replaced - *Continued*



Copper Water Pipes

Informational Conditions


The potable water pipes are in acceptable condition.

General Gas Components

Gas Main Shut-Off Location

Informational Conditions

The gas main shut-off is located in the side yard. You should be aware that gas leaks are not uncommon, particularly underground ones, and that they can be difficult to detect without the use of sophisticated instruments, which is why natural gas is odorized in the manufacturing process. Therefore, we recommend that you request a recent gas bill from the sellers, so that you can establish a norm and thereby be alerted to any potential leak.



Gas Main Observations

Informational Conditions

There is no wrench at the gas shut-off valve to facilitate an emergency shut-off, and inasmuch as such tools are relatively inexpensive we recommend that you buy one and leave it in-place on the valve.

Inspection Address: 3488Grand Teton Dr, Corona, CA 92881
Inspection Date/Time: 8/15/2016 10:00 am to 12:30 pm

Gas SupplyPipes

Informational Conditions

The visible portions of the gas pipes appear to be in acceptable condition.

Gas Water Heaters

General Comments

Informational Conditions

There are a wide variety of residential water heaters that range in capacity from fifteen to one hundred gallons. They can be expected to last at least as long as their warranty, or from five to eight years, but they will generally last longer. However, few of them last longer than fifteen or twenty years and many eventually leak. So it is always wise to have them installed over a drain pan plumbed to the exterior. Also, it is prudent to flush them annually to remove minerals that include the calcium chloride bi-product of many water softening systems. The water temperature should be set at a minimum of 110 degrees fahrenheit to kill microbes and a maximum of 140 degrees to prevent scalding. Also, water heaters can be dangerous if they are not seismically secured and equipped with either a pressure/temperature relief valve and discharge pipe plumbed to the exterior, or a Watts 210 gas shut-off valve.

Age Capacity & Location

Informational Conditions

Hot water is provided by a 3 year old, 50 gallon water heater that is located in the garage.



Common Observations

Functional Components and Conditions

There is possible damage to a gas pipe for the BBQ grill. A licensed plumber is recommended.

There is possible damage to a gas pipe for the BBQ grill - *Continued*



Informational Conditions

The water heater is not installed over a drain pan and a leak could result in water damage.

Water Shut-Off Valve & Connectors

Functional Components and Conditions

One hose bib is missing its valve and a licensed plumber is recommended.



Informational Conditions

The shut-off valve and water connectors are functional.

Gas Shut-Off Valve & Connector

Informational Conditions

The gas control valve and its connector at the water heater are functional.

Vent Pipe & Cap

Informational Conditions

The vent pipe is functional.

Relief Valve & Discharge Pipe

Functional Components and Conditions

The water heater is equipped with a mandated pressure-temperature relief valve.

Drain Valve

Informational Conditions

The drain valve is in place and presumed to be functional.

Drain Pan & Discharge Pipe

Components and Conditions Needing Service

The water heater is not equipped with a drain pan and overflow pipe, which is mandated in locations where water could cause structural damage, and should be installed as soon as conveniently possible.

Combustion Air Vents

Functional Components and Conditions

The water heater does have appropriate combustion-air vents.

Seismic Straps

Informational Conditions

The water heater is seismically secured.

Solar Assisted

Informational Conditions

The plumbing system includes a solar system, which we do not have the expertise to evaluate, and which we specifically disclaim. Therefore, you may wish to have a specialist evaluate.

Electric Water Heaters

Solar Assisted

Informational Conditions

The plumbing system includes a solar system, which we do not have the expertise to evaluate, and which we specifically disclaim. Therefore, you may wish to have a specialist evaluate.

Irrigation or Sprinklers

General Comments

Informational Conditions

There are a wide variety of irrigation components, such as pipes that could include old galvanized ones, more dependable copper ones, and modern polyvinyl ones that are commonly referred to as PVC. However, among the latter, the quality can range from a dependable thick-walled type to a less dependable thin-walled type, and it is not uncommon to find a mixture of them. To complicate matters, significant portions of these pipes cannot be examined because they are buried. Therefore, we identify a system based on what type of pipe that can be seen. However, our inspection only includes the visible portions of the system, and we do not test each component, nor search below vegetation for any concealed hose bibs, actuators, risers, or heads. We test every visually accessible manual sprinkler actuator and evaluate its coverage, but due to the variety and complexity of many automatic control panels we do not test them. However, inasmuch as the actuators are under pressure, we look for any evidence of damage or leakage, but recommend that you have the sellers demonstrate an automatic sprinkler system before the close of escrow and indicate any seasonal changes that they may make to the program.

Automatic Sprinklers

Functional Components and Conditions

We do not evaluate sprinkler systems but there are several broken pvc pipes broken.

Inspection Address: 3488Grand Teton Dr, Corona, CA 92881
Inspection Date/Time: 8/15/2016 10:00 am to 12:30 pm

We do not evaluate sprinkler systems but there are several broken PVC pipes broken - *Continued*



Informational Conditions

We do not evaluate sprinkler systems, which should be demonstrated by the sellers.



Waste & Drainage Systems

General Comments

Functional Components and Conditions

The main clean out is located in the garage.

The main clean out is located in the garage - *Continued*



Electrical

There are a wide variety of electrical systems with an even greater variety of components, and any one particular system may not conform to current standards or provide the same degree of service and safety. What is most significant about electrical systems however is that the national electrical code [NEC] is not retroactive, and therefore many residential systems do not comply with the latest safety standards. Regardless, we are not electricians and in compliance with our standards of practice we only test a representative number of switches and outlets and do not perform load-calculations to determine if the supply meets the demand. However, in the interests of safety, we regard every electrical deficiency and recommended upgrade as a latent hazard that should be serviced as soon as possible, and that the entire system be evaluated and certified as safe by an electrician. Therefore, it is essential that any recommendations that we may make for service or upgrades should be completed before the close of escrow, because an electrician could reveal additional deficiencies or recommend some upgrades for which we would disclaim any further responsibility. However, we typically recommend upgrading outlets to have ground fault protection, which is a relatively inexpensive but essential safety feature. These outlets are often referred to as GFCI's, or ground fault circuit interrupters and, generally speaking, have been required in specific locations for more than thirty years, beginning with swimming pools and exterior outlets in 1971, and the list has been added to ever since: bathrooms in 1975, garages in 1978, spas and hot tubs in 1981, hydro tubs, massage equipment, boat houses, kitchens, and unfinished basements in 1987, crawlspaces in 1990, wet bars in 1993, and all kitchen countertop outlets with the exception of refrigerator and freezer outlets since 1996. Similarly, AFCI's or arc fault circuit interrupters, represent the very latest in circuit breaker technology, and have been required in all bedroom circuits since 2002. However, inasmuch as arc faults cause thousands of electrical fires and hundreds of deaths each year, we categorically recommend installing them at every circuit as a prudent safety feature.

Main Panel

General Comments

Informational Conditions

National safety standards require electrical panels to be weatherproof, readily accessible, and have a minimum of thirty-six inches of clear space in front of them for service. Also, they should have a main disconnect, and each circuit within the panel should be clearly labeled. Industry standards only require us to test a representative number of accessible switches, receptacles, and light fixtures. However, we attempt to test every one that is unobstructed, but if a residence is furnished we will obviously not be able to test each one.

Service Entrance


Informational Conditions

The service entrance, mast weather head, and cleat are in acceptable condition.

Panel Size & Location

Informational Conditions

The residence is served by a 200 amp, located in the house side yard.



Main Panel Observations

Informational Conditions

The panel and its components have no visible deficiencies.

Panel Cover Observations

Informational Conditions

The exterior panel cover is in acceptable condition.

Wiring Observations

Informational Conditions

The visible portions of the wiring has no visible deficiencies.

Circuit Breakers

Informational Conditions

There are no visible deficiencies with the circuit breakers.

Grounding

Informational Conditions

The panel is grounded to a water pipe. Current standards require the panel to be double-grounded, and you may wish to consider having this done as a safety upgrade. However, such an upgrade is not currently mandated.

Heat and Air Conditioning

The components of most heating and air-conditioning systems have a design-life ranging from ten to twenty years, but can fail prematurely with poor maintenance, which is why we apprise you of their age whenever possible. We test and evaluate them in accordance with the standards of practice, which means that we do not dismantle and inspect the concealed portions of evaporator and condensing coils, the heat exchanger, which is also known as the firebox, electronic air-cleaners, humidifiers, ducts and in-line duct-motors or dampers. We perform a conscientious evaluation of both systems, but we are not specialists. However, even the most modern heating systems can produce carbon monoxide, which in a sealed or poorly ventilated room can result in sickness, debilitating injury, and even death. Therefore, in accordance with the terms of our contract, it is essential that any recommendations that we make for service or a second opinion be scheduled before the

Inspection Address: 3488Grand Teton Dr, Corona, CA 92881
Inspection Date/Time: 8/15/2016 10:00 am to 12:30 pm


close of escrow, because a specialist could reveal additional defects or recommend further upgrades that could affect your evaluation of the property, and our service does not include any form of warranty or guarantee.

HVAC Split Systems

Common Observations

Functional Components and Conditions

It is recommended the air conditioning and heating be inspected by licensed contractor the gas was off and the heating was not tested the a/c part was tested but would turn on and off we recommended the unit and its componts be inspected by a licensed contractor



It is recommended the filters are changed every 3 to 6 months.

Informational Conditions

It is recommended the filters should be replaced

Components and Conditions Needing Service

For the reasons indicated, the split-system needs to be serviced. This service should be scheduled within the inspection period, because a specialist might reveal additional defects or recommend upgrades that could affect your evaluation of the systems.

Furnace

Informational Conditions

The furnace is functional.

Vent Pipe

Informational Conditions

The vent pipe has no visible deficiencies.

Circulating Fan

Informational Conditions

The circulating fan is clean and functional.

Gas Valve & Connector

Informational Conditions

The gas valve and connector are in acceptable condition.

Combustion-Air Vents

Informational Conditions

The combustion-air vents appear to be adequate to support complete combustion.

Return-Air Compartment

Informational Conditions

The return-air compartment is in acceptable condition.

Evaporator Coil

Informational Conditions

The evaporator coil is functional.

Condensate Drainpipe

Informational Conditions

The condensate drainpipe discharges correctly outside the residence.

Drip Pan

Components and Conditions Needing Service

There is no drip pan beneath the evaporator coil at the horizontal furnace. Although such an installation is not mandated, it is a sensible feature and one that is commonly recommended.

Condensing Coil

Informational Conditions

The condensing coil responded to the thermostat and is functional.

Condensing Coil Disconnect

Informational Conditions

The electrical disconnect at the condensing coil is functional.

Refrigerant Lines

Informational Conditions

The refrigerant lines are in acceptable condition.

Thermostats

Informational Conditions

The thermostat is functional.

Registers

Informational Conditions

The registers are reasonably clean and functional.

Flexible Ducting

Informational Conditions

The ducts have no visible deficiencies. They are a modern flexible type that are comprised of an outer plastic sleeve and a clear inner liner that contains fiberglass insulation.

The flexible ducts have no visible deficiencies - *Continued*



Living Areas

Our inspection of living space includes the visually accessible areas of walls, floors, cabinets and closets, and includes the testing of a representative number of windows and doors, switches and outlets. However, we do not evaluate window treatments, or move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on cosmetic deficiencies. We may not comment on the cracks that appear around windows and doors, or which follow the lines of framing members and the seams of drywall and plasterboard. These cracks are a consequence of movement, such as wood shrinkage, common settling, and seismic activity, and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist. Similarly, there are a number of environmental pollutants that we have already elaborated upon, the specific identification of which is beyond the scope of our service but which can become equally contentious. In addition, there are a host of lesser contaminants, such as that from moisture penetrating carpet-covered cracks in floor slabs, as well as odors from household pets and cigarette smoke that can permeate walls, carpets, heating and air conditioning ducts, and other porous surfaces, and which can be difficult to eradicate. However, inasmuch as the sense of smell adjusts rapidly, and the sensitivity to such odors is certainly not uniform, we recommend that you make this determination for yourself, and particularly if you or any member of your family suffers from allergies or asthma, and then schedule whatever remedial services may be deemed necessary before the close of escrow.

Indoor Environmental Issues

Environmental Observations

Informational Conditions

We do not test for mold or measure indoor air quality, which the Consumer Product safety Commission ranks fifth among potential contaminants. Regardless, a person's health is a truly personal responsibility, and inasmuch as we not inspect for mold or test for other environmental contaminants we recommend that you schedule an inspection by an environmental hygienist before the close of escrow. And this would be imperative if you or any member of your family suffers from allergies or asthma, and could require the sanitizing of air ducts and other concealed areas.

Note: Mold cannot exist without moisture. Therefore, any moisture whatsoever, whether it be from inadequate grading and drainage, a leaking roof, window, or door, or moisture from a faulty exhaust vent, a condensate pipe, an evaporator coil, or a component of a plumbing system should be serviced immediately, or the potential for mold infestation will remain.

Vermin and other pests are part of the natural habitat, but they often invade homes. Rats and mice have collapsible rib-cages and can enter even the tiniest crevices. And it is not uncommon for them to establish colonies within crawlspaces, attic, closets, and even inside walls, where they can breed and become a health threat. Therefore, it would be prudent to make sure that a home is rodent-proof, and to monitor those areas that are not readily accessible.

Main Entry

Furnished Residence Comment

Informational Conditions

The residence is furnished, and in accordance with industry standards we only inspect those surfaces that are exposed and readily accessible. We do not move furniture, lift carpets, nor remove or rearrange items within closets and cabinets.

Doors

Functional Components and Conditions

The door is functional.

Flooring


Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.



Lights

Functional Components and Conditions

The lights are functional.

Dining Room

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.



Dual-Glazed Windows

Functional Components and Conditions

The windows are functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional.

Family Room

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.



Dual-Glazed Windows

Functional Components and Conditions

The window is functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional.

Game Room

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.



Dual-Glazed Windows

Functional Components and Conditions

The window is functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional.

Office or Library

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling in the library are in acceptable condition.



Dual-Glazed Windows

Functional Components and Conditions

The window is functional.

Lights

Functional Components and Conditions

The lights in the library are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional.

Kitchen

We test kitchen appliances for their functionality, and cannot evaluate them for their performance nor for the variety of their settings or cycles. However, if they are older than ten years, they may well exhibit decreased efficiency. Also, many older gas and electric ranges are not secured and can be easily tipped, particularly when any weight is applied to an open range door, and all such appliances should be confirmed to be secure. Regardless, we do not inspect the following items: free-standing appliances, refrigerators, trash-compactors, built-in toasters, coffee-makers, can-openers, blenders, instant hot-water dispensers, water-purifiers, barbecues, grills or rotisseries, timers, clocks, thermostats, the self-cleaning capability of ovens, and concealed or countertop lighting, which is convenient but often installed after the initial construction and not wired to national electrical standards.

Kitchen

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Functional Components and Conditions

The walls and ceiling are in acceptable condition.



Dual-Glazed Windows

Functional Components and Conditions

The window is functional.

Sink & Countertop

Informational Conditions

The sink and countertop are functional.

Cabinets

Functional Components and Conditions

The cabinets are functional, and do not have any significant damage.



Valves & Connectors

Functional Components and Conditions

The valves and connectors below the sink are functional. However, they are not in daily use and will inevitably become stiff or frozen.

Informational Conditions

The valves needs to be properly sealed



Faucet

Functional Components and Conditions

The sink faucet is functional.

Trap and Drain

Functional Components and Conditions

The trap and drain are functional.

Garbage Disposal

Functional Components and Conditions

The garbage disposal is functional.

Gas Cooktop

Functional Components and Conditions

The gas cook top is functional.



Components and Conditions Needing Service

The gas cook top is probably the same age as the residence, and should not be expected to last indefinitely.

Built-in Electric Oven

Functional Components and Conditions

The electrical oven is functional, but was neither calibrated nor tested for its performance.



Dishwasher

Functional Components and Conditions

The dishwasher is functional.



Exhaust Fan or Downdraft

Functional Components and Conditions

The exhaust fan or downdraft is functional.

Built-in Microwave

Functional Components and Conditions

The built-in microwave is functional but we did not test it for leakage, which would require a specialized instrument.

The built-in microwave is functional - *Continued*



Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional and include ground-fault protection.

Refrigerator

Functional Components and Conditions

The refrigerator is functional.



Sliding Glass Door

Functional Components and Conditions

The sliding screen door is missing.

The sliding screen door is missing - *Continued*



Hallway

Our evaluation of hallways is identical to that of living space, except that we pay particular attention to safety issues, such as those involving handrails, guardrails, and smoke detectors.

Primary Hallway

Flooring


Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.



Lights

Functional Components and Conditions

The lights are functional.

Smoke Detector

Informational Conditions

We do not evaluate smoke detectors as part of our service. However, they are an important safety feature that is required in many jurisdictions, and should be installed or certified as being compliant.

Stairs

Our evaluation of staircases is identical to that of living space, except that we pay particular attention to safety issues, such as those involving handrails, guardrails, and smoke detectors.

Main Stairs

No Recommended Service

Informational Conditions

We have evaluated the stairs and landing, and found them to be in acceptable condition.

Floor Treads & Risers


Informational Conditions

There are audible sub-floor squeaks on the landing at the top of the stairs, or at points on the second floor. They result when the sub-floor separates slightly from the floor joists and then rubs up and down on the fasteners that hold it in place. This condition can be usually eliminated by adding pre-drilled screws close to the fasteners.

Walls & Ceiling

Informational Conditions

The walls and ceiling have no significant defects.



Handrails & Guardrails

Informational Conditions

If small children occupy or visit this residence, suitable precautions should be taken to safeguard them.

Lights

Functional Components and Conditions

The lights are functional.

Smoke Detector

Informational Conditions

We do not evaluate smoke detectors as part of our service. However, they are an important safety feature that is required in many jurisdictions, and should be installed or certified as being compliant.

Attic

In accordance with our standards, we do not attempt to enter attics that have less than thirty-six inches of headroom, are restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we would inspect them as best we can from the access point. In regard to evaluating the type and amount of insulation on the attic floor, we use only generic terms and approximate measurements, and do not sample or test the material for specific identification. Also, we do not disturb or move any portion of it, and it may well obscure water pipes, electrical conduits, junction boxes, exhaust fans, and other components.

Primary Attic

Attic Access Location

Informational Conditions

The attic can be accessed through a hatch in the hallway ceiling.



Method of Evaluation

Informational Conditions

We evaluated the attic by direct access.

Common Observations

Components and Conditions Needing Service

There is miscellaneous construction debris on the attic floor, which should be removed.

There is miscellaneous construction debris on the attic floor which should be removed - *Continued*



Framing

Informational Conditions

The visible portions of the conventionally stacked roof framing are in acceptable condition, and would conform to the standards of the year in which they were installed.

Ventilation

Informational Conditions

Ventilation is provided by a combination of eave, dormer, turbine, or gable vents, and should be adequate.

Electrical

Informational Conditions

The electrical components that are fully visible appear to be in acceptable condition.

Heat Vents

Informational Conditions

The heat vents appear to be functional.

Plumbing Vents

Informational Conditions

The drainpipe vents that are fully visible are in acceptable condition.

Exhaust Ducts

Informational Conditions

The visible portions of the exhaust ducts are functional.

Water Pipes

Informational Conditions

The visible portions of the water pipes are in acceptable condition, but should be monitored because of their location. Leaks from pipes that pass through an attic can be soaked up by insulation, and are difficult to detect until significant damage is evident elsewhere.

Blown-In Cellulose Insulation

Informational Conditions

The attic is adequately insulated, but not necessarily to a maximum standard. The amount of insulation can range from three to eighteen inches, depending upon the climate, the region, and the year in which the residence was constructed.

Bedrooms

In accordance with the standards of practice, our inspection of bedrooms includes the visually accessible areas of walls, floors, cabinets and closets, and includes the testing of a representative number of windows and doors, switches and outlets. We evaluate windows to ensure that they meet light and ventilation requirements and facilitate an emergency exit or egress, but we do not evaluate window treatments, nor move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on common cosmetic deficiencies.

Master Bedroom

Location

Informational Conditions

The master bedroom is located on the 2nd floor.



Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.

Dual-Glazed Windows

Informational Conditions

The windows that were unobstructed were checked, and found to be functional.

Closets

Functional Components and Conditions

The closet and its components are functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were unobstructed and able to be tested are functional.

Smoke Detector

Informational Conditions

We do not evaluate smoke detectors as part of our service. However, they are an important safety feature that is required in many jurisdictions, and should be installed or certified as being compliant.

1st Guest Bedroom

Location

Functional Components and Conditions

The 1st Guest Bedroom is located downstairs by the family room.

Doors

Functional Components and Conditions

The door is functional.

Flooring

Functional Components and Conditions

The floor has no significant defects.

Walls and Ceilings

Functional Components and Conditions

The walls and ceiling are in acceptable condition.



Dual-Glazed Windows

Functional Components and Conditions

The windows that were unobstructed were checked and found to be functional.

Closets

Functional Components and Conditions

The closet and its components are functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were unobstructed and able to be tested are functional.

Smoke Detector

Functional Components and Conditions

We do not evaluate smoke detectors as part of our service. However, they are an important safety feature that is required in many jurisdictions, and should be installed or certified as being compliant.

2nd Guest Bedroom

Location

Informational Conditions

The 2nd guest bedroom is adjacent to the guest hall bathroom.

Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.



Dual-Glazed Windows

Informational Conditions

The windows that were unobstructed were checked, and found to be functional.

Closets

Functional Components and Conditions

The closet and its components are functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were unobstructed and able to be tested are functional.

Smoke Detector

Informational Conditions

We do not evaluate smoke detectors as part of our service. However, they are an important safety feature that is required in many jurisdictions, and should be installed or certified as being compliant.

3rd Guest Bedroom

Location

Informational Conditions

The 3rd guest bedroom is adjacent to the hall bathroom.

Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.



Dual-Glazed Windows

Informational Conditions

The windows that were unobstructed were checked, and found to be functional.

Closets

Functional Components and Conditions

The closet and its components are functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were unobstructed and able to be tested are functional.

Smoke Detector

Informational Conditions

We do not evaluate smoke detectors as part of our service. However, they are an important safety feature that is required in many jurisdictions, and should be installed or certified as being compliant.

4th Guest Bedroom

Location

Informational Conditions

The 4th guest bedroom is adjacent to the Master bedroom.

Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.



Dual-Glazed Windows

Informational Conditions

The windows that were unobstructed were checked, and found to be functional.

Closets

Functional Components and Conditions

The closet and its components are functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were unobstructed and able to be tested are functional.

Smoke Detector

Informational Conditions

We do not evaluate smoke detectors as part of our service. However, they are an important safety feature that is required in many jurisdictions, and should be installed or certified as being compliant.

Game Room

No Recommended Service

Functional Components and Conditions

The window and screen appear to be functional

Bathrooms

In accordance with industry standards, we do not comment on common cosmetic deficiencies, and do not evaluate window treatments, steam showers, and saunas. More importantly, we do not leak-test shower pans, which is usually the responsibility of a termite inspector. However, because of the possibility of water damage, most termite inspectors will not leak-test second floor shower pans without the written consent of the owners or occupants.

Master Bathroom

Size and Location

Informational Conditions

The master bathroom is a full, and is located adjacent to the master bedroom.

A Probable Remodel

Informational Conditions

The master bathroom appears to have been remodeled. Therefore, you should obtain documentation for your records so that you can be assured that the work was done with permit to professional standards, because we do not approve of, or tacitly endorse, any work that was done without permit, and latent defects could exist.

Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.

The walls and ceiling are in acceptable condition - *Continued*



Dual-Glazed Windows

Functional Components and Conditions

The window is functional.

Cabinets

Functional Components and Conditions

The cabinets are in acceptable condition.

Sink Countertop

Functional Components and Conditions

The sink countertop is functional.

Sink Faucet Valves & Connectors Trap & Drain

Functional Components and Conditions

The sink and its components are functional.

Hydro-Spa

Functional Components and Conditions

The hydro-spa is functional but should be flushed with a cleanser if not used frequently.



Stall Shower

Functional Components and Conditions

The stall shower is functional.



Toilet & Bidet

Functional Components and Conditions

The toilet is functional.

Exhaust Fan

Functional Components and Conditions

The exhaust fan is functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets are functional and include ground-fault protection.

Hall Bathroom

Size and Location

Functional Components and Conditions

The hall bathroom is full and is located between bedroom 2 and bedroom 3.

Doors

Functional Components and Conditions

The door is functional

Flooring

Informational Conditions

The floor has no significant defects

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition

The walls and ceiling are in acceptable condition - *Continued*



Dual-Glazed Windows

Functional Components and Conditions

The window is functional.

Cabinets

Functional Components and Conditions

The cabinets are in acceptable condition.

Sink Countertop

Functional Components and Conditions

The sink countertop is functional.

Sink Faucet Valves & Connectors Trap & Drain

Functional Components and Conditions

The sink and its components are functional.

The pop up drain is not connected properly to the faucet. A licensed plumber is recommended.



Tub-Shower

Functional Components and Conditions

The tub/shower is functional.



Toilet & Bidet

Functional Components and Conditions

The toilet is functional.



Exhaust Fan

Functional Components and Conditions

The exhaust fan is functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets are functional and include ground-fault protection.

Hall Bathroom Downstairs

Doors

Functional Components and Conditions

The door is functional.

Flooring

Functional Components and Conditions

The floor has no significant defects.

Walls & Ceilings

Functional Components and Conditions

The walls and ceiling are in acceptable condition.



Sink Countertops

Functional Components and Conditions

The sink countertop is functional.

Sink Faucet Valves & Connectors Trap & Drain

Functional Components and Conditions

The sink and its components are functional.

Stall Shower

Functional Components and Conditions

The stall shower is functional.

Toilet & Bidet

Functional Components and Conditions

The toilet is functional.

Exhaust Fan

Functional Components and Conditions

The exhaust fan is functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets are functional and include ground-fault protection.

Laundry

In accordance with industry standards, we do not test clothes dryers, nor washing machines and their water connections and drainpipes. However, there are two things that you should be aware of. The water supply to washing machines is usually left on, and their hoses can leak or burst under pressure and continue to flow. Therefore, we recommend replacing the rubber hose type with newer braided stainless steel ones that are much more dependable. You should also be aware that the newer washing machines discharge a greater volume of water than many of the older drainpipes can handle, which causes the water to back up and overflow, and the only remedy would be to replace the standpipe and trap with one that is a size larger.

Laundry Room

Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.

The walls have typical cosmetic damage.



Cabinets

Functional Components and Conditions

The cabinets are functional.

Sink

Functional Components and Conditions

The laundry sink is functional, and does not need service at this time.

Faucet

Functional Components and Conditions

The laundry sink faucet is functional.

Valves & Connectors

Functional Components and Conditions

The valves and connectors are functional. However, because they are not in daily use they typically become stiff or frozen.

Trap & Drain

Functional Components and Conditions

The trap and drain are functional.

Gas Valve & Connector

Informational Conditions

The gas valve and connector are functional.

Dryer Vent

Informational Conditions

Faulty dryer vents have been responsible for thousands of fires, hundreds of injuries, and even deaths. The best vents are a smooth-walled metal type that travels a short distance; all other types should be regarded as suspect, and should be inspected bi-annually to ensure that they do not contain trapped lint or moisture.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional.

Garage

It is not uncommon for moisture to penetrate garages, because their slabs are on-grade. Evidence of this is typically apparent in the form of efflorescence, or salt crystal formations, that result when moisture penetrates the concrete slab or sidewalls. This is a common with garages that are below grade, and some sidewalls are even cored to relieve the pressure that can build up behind them, and which actually promotes drainage through the garage. Also, if there is living space above the garage, that space will be seismically vulnerable. Ideally, the columns and beams around the garage door will be made of structural steel, but in many residences these components are made of wood but could include some structural accessories, such as post-straps and hold-downs, and plywood shear paneling. However, we are not an authority in such matters, and you may wish to discuss this further with a structural engineer. In addition, and inasmuch as garage door openings are not standard, you may wish to measure the opening to ensure that there is sufficient clearance to accommodate your vehicles.

Triple-Car Garage

Parking Space

Informational Conditions

The parking space has been restricted by the addition of storage shelves or a workbench. Therefore, it would be prudent for you to see that the parking space is adequate to accommodate your vehicles.

The parking space has been restricted by the addition of storage shelves or a workbench - *Continued*



Slab Floor

Functional Components and Conditions

The slab floor is in acceptable condition. Small cracks are common and result as a consequence of the curing process, seismic activity, common settling, or the presence expansive soils, but are not structurally threatening. Also, you may notice some salt crystal formations that are activated by moisture penetrating the slab.

Walls & Ceiling

Informational Conditions

The walls and ceiling are sheathed and in acceptable condition.

Components and Conditions Needing Service

There is evidence of moisture intrusion in the garage. However, it is not uncommon to find such evidence in the form of efflorescence, or salt crystal formations, on the walls and slab of a garage. Garages are built on-grade, and most will be subject to some degree of moisture intrusion when it is raining. In spite of this, many older garages will not have a moisture barrier beneath the slab and, if they are below grade, the walls may not have been treated to resist moisture. However, you may wish to ask the sellers about this condition or have it evaluated by a grading and drainage contractor.



Dual-Glazed Windows

Functional Components and Conditions

The window is functional.

Ventilation Ports

Functional Components and Conditions

The ventilation ports are functional.

Firewall Separation

Functional Components and Conditions

The firewall separating the garage from the residence is functional.

Entry Door Into the House

Functional Components and Conditions

The house entry door is solid core, or fire-rated, and self-closes in conformance with fire-safety regulations.

Garage Side Door

Functional Components and Conditions

The side door is functional.

Garage Door & Hardware

Functional Components and Conditions

The garage door and its hardware are functional.



Automatic Opener

Functional Components and Conditions

The garage door opener is functional.

Lights

Functional Components and Conditions

The lights are functional, and do not need service at this time.

Outlets

Functional Components and Conditions

The outlets that were tested are functional, and include ground-fault protection.

An outlet is missing a cover plate and should be covered.

An outlet is missing a cover plate and should be covered - *Continued*



Pool and Spa

Pools and spas do leak, but without specialized equipment this may be impossible to confirm. However, it could become apparent from secondary evidence during our inspection, which is purely visual. Regardless, the owner or the occupant of a property would be aware that the water level drops regularly and must be topped off, and this should be disclosed. Unusually high water bills could reveal this, but only a pressure test of the pipes, a dye test of cracks, or a geo-phone test of specific areas would confirm it, and any such specialized test is beyond the scope of our service. Therefore, you should ask the sellers to guarantee that the spa does not leak, request to review the water bills for a twelve-month period, or obtain comprehensive insurance to cover such an eventuality.

Pool & Spa

General Comments

Informational Conditions

The interior finish of pools and spas is rarely perfect and rarely remains so, and particularly those on pools with colored plasters, and certainly if the chemical balance of the water is not properly maintained. Also, calcium and other minerals will have a tendency to leech through the material and mar the finish. This is equally true of pool tiles, on which mineral scaling is not only common but difficult to remove. Even the harshest abrasives will not remove some scaling, which sometimes has to be removed by bead-blasting, which in turn reduces the luster of the tiles. However, such imperfections have only a cosmetic significance. Similarly, the decks around pools and spas tend to develop cracks that have only a cosmetic significance. The commonest are relatively small, and are often described as being curing fractures. Some of these will contour the outline of the pool, or the point at which the bond beam, or structural wall of the pool, meets the surrounding soil. These too have little structural significance, but some cracks are larger and result from seismic motion, or from settling due to poorly compacted soils, or they confirm the presence of expansive soils, which can be equally destructive, but which should be confirmed by a geo-structural engineer. However, any crack in the shell of a pool or spa should be dye-tested or otherwise evaluated by a specialist.

Enclosure Safety Observations

Informational Conditions

The pool enclosure is currently compliant with common safety standards, which typically mandate a forty-eight inch enclosure, measured on the side away from the water, so that a toddler could not simply push open an unlatched gate.

Pool & Spa Observations

Functional Components and Conditions

The pool and spa are in acceptable condition. Recommend a licensed pool contractor to evaluate the chemicals, changing the water, and the cleaning service.

Informational Conditions

The pool and spa employ remote controls, which we do not evaluate, but which should be demonstrated by the sellers.

Interior Finish

Informational Conditions

The interior finish is Pebble-tec, which is in acceptable condition. Pebble-tec is a popular and durable pool finish, because it can be exposed to air, and is commonly installed without tiles.

Deck & Coping Stones

Informational Conditions

The deck is in acceptable condition.

Expansion Joint

Informational Conditions

The expansion joint is in good condition.

Skimmer

Informational Conditions

The skimmer box and its cover are functional.

Pool-Spa Motors

Functional Components and Conditions

The spa and pool motor and equipment are functional but recommend a licensed pool contractor for further evaluation.



Supply & Return Lines Etc

Informational Conditions

The visible portions of the supply and return lines and their valves are in acceptable condition.

Filter

Informational Conditions

The filter is functional.

Solar System

Informational Conditions

The pool equipment includes a solar system that we do not have the expertise to evaluate, which you may wish to have evaluated by a specialist.

Inspection Address: 3488Grand Teton Dr, Corona, CA 92881
Inspection Date/Time: 8/15/2016 10:00 am to 12:30 pm

Electrical Issues

Informational Conditions

The outlets in the general vicinity of the pool and spa are functional.

REPORT CONCLUSION

3488Grand Teton Dr, Corona, CA 92881

NOTES:

There are typical cosmetic damage to the home according to the age of the property.

The vegetation and trees should be pruned and monitored. There are some palm trees that are close to the property.

Recommend a licensed roofer for further evaluation.

Recommend a licensed plumber for further evaluation.

Recommend a licensed AC/Heating contractor to evaluate the components.

Recommend the chimney to be cleaned.

Recommend a licensed pool/spa contractor.

The fences need to be repaired or replaced.

The main clean out is located in the garage.

There is evidence of moisture in certain areas of the house due to the sprinklers

We do not evaluate solar panels.

Congratulations on the purchase of your new home. In as much as we never know who will be occupying or visiting a property, whether it be children or the elderly, we ask you to consider following these general safety recommendations: install smoke and carbon monoxide detectors; identify all escape and rescue ports; rehearse an emergency evacuation of the home; upgrade older electrical systems by at least adding ground-fault outlets; never service any electrical equipment without first disconnecting its power source; safety-film all non-tempered glass; ensure that every elevated window and the railings of stairs, landings, balconies, and decks are child-safe, meaning that barriers are in place or that the distance between the rails is not wider than three inches; regulate the temperature of water heaters to prevent scalding; make sure that goods that contain caustic or poisonous compounds, such as bleach, drain cleaners, and nail polish removers be stored where small children cannot reach them; ensure that all garage doors are well balanced and have a safety device, particularly if they are the heavy wooden type; remove any double-cylinder deadbolts from exterior doors; and consider installing child-safe locks and alarms on the exterior doors of all pool and spa properties.

We are proud of our service, and trust that you will be happy with the quality of our report. We have made every effort to provide you with an accurate assessment of the condition of the property and its components and to alert you to any significant defects or adverse conditions. However, we may not have tested every outlet, and opened every window and door, or identified every minor defect. Also because we are not specialists or because our inspection is essentially visual, latent defects could exist. Therefore, you should not regard our inspection as conferring a guarantee or warranty. It does not. It is simply a report on the general condition of a particular property at a given point in time. Furthermore, as a homeowner, you should expect problems to occur. Roofs will leak, drain lines will become blocked, and components and systems will fail without warning. For these reasons, you should take into consideration the age of the house and its components and keep a comprehensive insurance policy current. If you have been provided with a home protection policy, read it carefully. Such policies usually only cover insignificant costs, such as that of roofer service, and the representatives of some insurance companies can be expected to deny coverage on the grounds that a given condition was preexisting or not covered because of what they claim to be a code violation or a manufacture's defect. Therefore, you should read such policies very carefully, and depend upon our company for any consultation that you may need.

Thank you for taking the time to read this report, and call us if you have any questions or observations whatsoever. We are always attempting to improve the quality of our service and our report, and we will continue to adhere to the highest standards of the real estate industry and to treat everyone with kindness, courtesy, and respect.

TABLE OF CONTENTS

CONFIDENTIAL INSPECTION REPORT	1
GENERAL INFORMATION	2
SCOPE OF WORK	3
Exterior	5
Site & Other Observations	5
Grading & Drainage	6
House Wall Finish	7
Exterior Components	7
Structural	10
Various Hard Surfaces	11
Structural Elements	11
Slab Foundation	11
Roof/Attic	12
Concrete Tile Roof	12
Chimney	13
Family Room Chimney	13
Plumbing	15
Potable Water Supply Pipes	15
General Gas Components	16
Gas Water Heaters	17
Electric Water Heaters	19
Irrigation or Sprinklers	19
Waste & Drainage Systems	20
Electrical	21
Main Panel	21
Heat and Air Conditioning	22
HVAC Split Systems	23
Living Areas	25
Indoor Environmental Issues	25
Main Entry	26
Dining Room	26
Family Room	27
Game Room	28
Office or Library	29
Kitchen	29
Kitchen	30
Hallway	34
Primary Hallway	34
Stairs	35
Main Stairs	35
Attic	36
Primary Attic	36
Bedrooms	38
Master Bedroom	38
1st Guest Bedroom	39
2nd Guest Bedroom	40
3rd Guest Bedroom	41
4th Guest Bedroom	42
Game Room	43
Bathrooms	43

Inspection Address: 3488Grand Teton Dr, Corona, CA 92881
Inspection Date/Time: 8/15/2016 10:00 am to 12:30 pm

Master Bathroom	43
Hall Bathroom	45
Hall Bathroom Downstairs	48
Laundry	49
Laundry Room	49
Garage	50
Triple-Car Garage	50
Pool and Spa	53
Pool & Spa	53
Report Conclusion	56